

MB4/1-2-3-5-6-7
&
MB4/8-12
S.L. ϕ 1- ϕ 2
J.B. wiring v.3/2


Inner View

J2 = 21 Wires
J2* = 3

J2 = 10 Strips
J2* = 2

Inter
Lock
GND

J2 = 8 Cathodes
J2* = 4



Dest pin# B	Source pin# I.C.	Dest pin# A
1-2	3* 1*	1-2
3-4	5 2*	3-4
5-6	6 4	5-6
7-8	9 7	7-8
9-10	11 8	9-10
11-12	12 10	11-12
13-14	15 13	13-14
15-16	17 14	15-16
17-18	18 16	17-18
19-20	21 19	19-20
21-22	23 20	21-22
23-24	24 22	23-24
25-26	27* 25*	25-26
27-28	29 26	27-28
29-30	30 28	29-30
31-32	33 31	31-32
33-34	35 32	33-34
35-36	36 34	35-36
41-43	41 43	41-43
44-45	45 44	44-45
46-47	47 46	46-47
48-49	48 49	48-49
50-51	51* 50*	50-51
52-53	53* 52*	52-53

60 Box MB4/1÷7 ϕ
20 Box MB4/8-12 ϕ