

MB2 & MB4/10  
 S.L.  $\phi 1 - \phi 2$   
 J.B. wiring v.3/2

Inner View

J1 = 15  
 J1\* = 1

J2 = 6  
 J2\* = 2

J1 = 8

J2 = 2  
 J2\* = 2

J1 = 4  
 J1\* = 4


J2 = 4

Wires

Strips

Inter  
 Lock  
 GND

Cathodes



Dest pin# B	Source pin# I.C.	Dest pin# A
1-2	3* 1*	1-2
4	5 2*	4
5	6 4	5
7-8	9 7	7-8
10	11 8	10
11	12 10	11
13-14	15 13	13-14
16	17 14	16
17	18 16	17
19-20	21 19	19-20
22	23 20	22
23	24 22	23
25-26	27* 25*	25-26
28	29 26	28
29	30 28	29
31-32	33 31	31-32
34	35 32	34
35	36 34	35
41-43	41 43	41-43
44	45 44	44
46	47 46	46
47-49	48 49	47-49
50	51* 50*	50
52	53* 52*	52

120 Box MB2  $\phi$   
 20 Box MB4/10  $\phi$